

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/09/2019

Submitted Date:

09/09/2019

Document Number:

699300116**FIELD INSPECTION FORM**
 Loc ID 328996 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415493	WELL	TA	03/05/2019	OW	123-31096	CANNON W 15-21D	TA

General Comment:

Location

Lease Road:			
Type	Access		
comment:	weeds growing on access Rd.		
Corrective Action:	Comply with Rule 603.f, 10 days for weeds.	Date:	09/19/2019

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds growing on location.		
Corrective Action:	Comply with rule 603.f 10 days for weeds.	Date:	09/19/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused flowline parts stored on pallet and hanging by Heated horizontal separator.		
Corrective Action:	Comply with Rule 603.f 30 days for unused equipment when machinery is not required to remove the equipment.	Date:	10/09/2019
Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	10/09/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		

Comment:	Barbless wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbless wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		
Comment:	Automation		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV CONCRETE		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)	60 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: Shares with crude oil tank							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	300 BBLS	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment: Shares containment with produced water tanks							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	<100 BBLS	PBV CONCRETE		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)	53 bbl						
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment: Shares containment with crude oil tanks							
Corrective Action:						Date:	
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:							Date:
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:							Date:

Inspected FacilitiesFacility ID: 415493 Type: WELL API Number: 123-31096 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 9/9/19 at approximately 0930 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Cannon W #15-21D Kerr McGee, at API #05-123-31096 in Weld County Colorado.</p> <p>While there, I observed a TA wellsite.</p> <p>During this inspection the following compliance issues were observed:</p> <p>Housekeeping: weeds growing on rd. and loc. Comply with Rule 603.f 10 days for weeds CA date 9/19/2019 see photos #1 and 2.</p> <p>Housekeeping: unused equipment on loc. Comply with Rule 603.f 30 days for unused equip. When machinery isn't required to remove equip. CA date 10/9/2019 see photos #3, 9 and 12.</p> <p>Housekeeping: unused no LOTO Flow line risers. Comply with Rule 603.f for unused unmarked flow line risers 24hrs to LOTO. 30 days to remove riser. CA date 10/9/2019 see photos #4, 10, 13 and 14</p> <p>Well report shows it to be TA at the time of this inspection the well appears to be TA, all production equipment have been removed From WH.</p> <p>Form 5A was submitted on 3/5/2019 Doc. #401960836.</p> <p>Form 4 continued TA was submitted on 5/6/2019 Doc. # 402033829</p> <p>Form 21 MIT was submitted on 2/20/2019 Doc. # 401946333</p> <p>Location is dry, weather is clear.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	09/09/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402170927	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4932581
699300117	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4932577