

Inspection Photos

API: 05-071-06145

Operator: MERIDIAN OIL

Inspection Date: 9/12/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06145 | Date: 9/12/2019

Inspection Photos



Photo 1. Facing southwest along the reclaimed access road. Perennial vegetation is uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06145 | Date: 9/12/2019

Inspection Photos



Photo 2. Facing southwest along the reclaimed access road. Perennial vegetation is uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06145 | Date: 9/12/2019

Inspection Photos



Photo 3. Facing west along the reclaimed access road. Perennial vegetation is uniformly established.



Inspection Photos



Photo 4. Facing west along the reclaimed access road. Perennial vegetation is uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06145 | Date: 9/12/2019

Inspection Photos



Photo 5. Facing west along the reclaimed access road. Perennial vegetation is uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06145 | Date: 9/12/2019

Inspection Photos



Photo 6. Facing west toward the location. Perennial vegetation is uniformly established.



Inspection Photos



Photo 7. Facing east toward the location. Perennial vegetation is uniformly established.



Inspection Photos



Photo 8. Northwest side of the location. Wattles have been removed. No noxious weed issues were found.



Inspection Photos



Photo 9. Transect Reclaim on location facing SE.



Photo 10. Transect Reclaim on location facing NW.



Inspection Photos



Photo 11. Transect Reference facing E.



Photo 12. Transect Reference facing W.



