

Inspection Photos
Location Name: IRISH EYES 33-21 FOLLOWUP
API #: 05-071-08658
INSP. #:695101364



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN, CORRECTIVE ACTION FROM PREVIOUS INSPECTION HAS BEEN ADDRESSED.

Inspection Photos

Location Name: IRISH EYES 33-21 FOLLOWUP

API #: 05-071-08658

INSP. #:695101364



PHOTO 3: THIS IS A PHOTO AND CORRECTIVE ACTION FROM PREVIOUS INSPECTION DOC#695100599. SEDIMENT HAS FILLED STORMWATER DRAIN ON UPSLOPE SIDE OF PLUGGED CULVERT

PHOTO 4: THIS IS THE CURENVT PHOTO AND CORECTIVE ACTION FOR THIS INSPECTION. SEDIMENT HAS FILLED STORMWATER DRAIN ON UPSLOPE SIDE OF PLUGGED CULVERT. CLEAN AND MAINTAIN BMP DITCH PER RULE 1002.f. CA DATE 10-16-19

Inspection Photos

Location Name: IRISH EYES 33-21 FOLLOWUP

API #: 05-071-08658

INSP. #:695101364



PHOTO 5: THIS IS A PHOTO AND CORRECTIVE ACTION FROM PREVIOUS INSPECTION DOC#695100599. STORMWATER EROSION AROUND CULVERT OUTLET. Install or repair required BMPs per Rule 1002.f

PHOTO 6: THIS IS A CURRENT PHOTO AND CA FOR THIS INSPECTION. STORMWATER EROSION AROUND CULVERT OUTLET. Install or repair required BMPs per Rule 1002.f. CA DATE IS IMMEDIATELY BEGIN WORK TO REPAIR EROSION.

Inspection Photos

Location Name: IRISH EYES 33-21 FOLLOWUP

API #: 05-071-08658

INSP. #:695101364



**PHOTO 7: ANOTHER VIEW OF EROSION AROUND CULVERT
OUTLET.**

**PHOTO 8: ANOTHER VIEW OF EROSION AROUND CULVERT
OUTLET.**

Inspection Photos

Location Name: IRISH EYES 33-21 FOLLOWUP

API #: 05-071-08658

INSP. #:695101364



**PHOTO 9: EROSION IN BMP DITCH ALONG ROW
NORTHWEST OF LOCATION. REPAIR EROSION AND
INSTALL ADEQUATER BMP'S TO PREVENT OR
REDUCE EROSION, COMPLY WITH RULE 1002.f. CA
DATE 10-16-19**

**PHOTO 10: EROSION IN BMP DITCH ALONG ROW
NORTHWEST OF LOCATION. REPAIR EROSION AND
INSTALL ADEQUATER BMP'S TO PREVENT OR
REDUCE EROSION, COMPLY WITH RULE 1002.f. CA
DATE 10-16-19**

Inspection Photos

Location Name: IRISH EYES 33-21 FOLLOWUP

API #: 05-071-08658

INSP. #:695101364



Colorado Oil & Gas Conservation Commission
37.06769, -104.68198, 2182.0m, 284°
2019/09/16 12:12:20



Colorado Oil & Gas Conservation Commission
37.06671, -104.67607, 2125.0m, 188°
2019/09/16 12:19:24

**PHOTO 11: EROSION IN BMP DITCH ALONG ROW
NORTHWEST OF LOCATION. REPAIR EROSION AND
INSTALL ADEQUATE BMP'S TO PREVENT OR
REDUCE EROSION, COMPLY WITH RULE 1002.f. CA
DATE 10-16-19**

**PHOTO 12: UNUSED EQUIPMENT STORED ON
LOCATION. REMOVE UNUSED EQUIPMENT, COMPLY
WITH RULE 603.f. CA DATE 10-16-19**

Inspection Photos

Location Name: IRISH EYES 33-21 FOLLOWUP

API #: 05-071-08658

INSP. #:695101364



**PHOTO 13: GUY LINE ANCHOR MARKER IS DOWN.
INSTALL GUY LINE ANCHOR MARKER COMPLY WITH
RULE 1003.a. CA DATE 10-16-19**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources