

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2019

Submitted Date:

09/16/2019

Document Number:

680305578

**FIELD INSPECTION FORM**

Loc ID 312242 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 55030

Name of Operator: MCCARTNEY ENGINEERING LLC

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
McCartney, Ron	(303) 830-7208	ron@mccartneyengineering.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219789	WELL	SI	08/01/2016	OW	075-07216	RICE 2	UN

**General Comment:**

Routine Site Inspection 2019

Note to Operator: Please read FIR completely and send Form 42 response when all CA's have been performed for follow-up reinspection.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Lease road is heavily rutted, exhibiting erosion and lack of BMP's.			
Corrective Action	Repair and maintain lease roads per Rule 604 series.			Date: 10/14/2019
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Satisfactory			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Satisfactory			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	Well has been converted to IJ. Remove PJ from location.			
Corrective Action:	Remove unused equipment per Rule 603 series			Date: 12/16/2019
Type	DEBRIS			
Comment:	Remove cement from previous work-over conversion to IJ, dated 04/16/2019.			
Corrective Action:	Remove surface debris/trash per Rule 604 series.			Date: 09/27/2019
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type				
Comment:				
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Other		# 0		
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 219789 Type: WELL API Number: 075-07216 Status: SI Insp. Status: UN**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_

(e.g. 30 psig or -30" Hg)

Inj Zone: DSNDTC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 04/16/2019

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Well has been converted to IJ. Update well file/well status/production reports.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Well has been converted to IJ since April 2019.  
NOTE TO OPERATOR: Update/change well status on COGCC database.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	Fail			

Comment: [Use BMP's for erosion management.](#)

Corrective Action: [Lease road is exhibiting rutting from erosion. Repair \(fill ruts\) and grade, maintain lease road per Rule 1002 series.](#)

Date: 10/14/2019

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680305579	Wellhead - PJ (unused equipment)	<a href="#">09-11-2019 048.JPG</a>
680305580	Debris	<a href="#">09-11-2019 050.JPG</a>