

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2019

Submitted Date:

09/17/2019

Document Number:

680305582**FIELD INSPECTION FORM**

Loc ID 312243 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 55030Name of Operator: MCCARTNEY ENGINEERING LLCAddress: 4251 KIPLING ST STE 575City: WHEAT RIDGE State: CO Zip: 80033**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
McCartney, Ron	(303) 830-7208	ron@mccartneyengineering.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219791	WELL	PR	07/01/2018	OW	075-07221	RICE 3	PR

General Comment:

Routine Site Inspection

NOTE TO OPERATOR: Read FIR completely and submit a Form 42 confirming CA's have been performed to schedule follow-up reinspection.

Contact COGCC Flow-line group for directives.

Location**Lease Road:**

Type	Access		
comment:	Repair and maintain lease road.		
Corrective ActionL		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	219791	Type:	WELL	API Number:	075-07221	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	OGW								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Gravel	Fail			

Comment: Heavily rutted lease road.Corrective Action: Fill ruts, grade and maintain lease roads per Rule 604 series.Date: 10/14/2019**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<u>Note to Operator: Please read FIR completely and perform CA's. Submit Form 42 verifying CA's have been performed for reinspection.</u>	schureky	09/17/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680305607	Signage, tubing/rods, debris	09-11-2019 034.JPG
680305608	PJ	09-11-2019 036.JPG
680305609	Stained soil @ wellhead	09-11-2019 037.JPG
680305611	Unidentified riser (NG line)	09-11-2019 033.JPG