

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/09/2019

Submitted Date:

09/09/2019

Document Number:

679601523**FIELD INSPECTION FORM**
 Loc ID 432871 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**20 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432869	WELL	PR	07/12/2015	OW	123-37329	Alm 33V-404	PR
432870	WELL	SI	05/01/2018	OW	123-37330	ALM 33W-314	TA
432872	WELL	PR	07/09/2015	OW	123-37331	Alm 33W-404	PR
432873	WELL	PR	07/12/2015	OW	123-37332	Alm 33V-234	PR
446738	TANK BATTERY	AC	03/28/2016		-	Alm 33V-234	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate (x4)		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	One wellhead (ALM 33W-314) contains unused equipment inside fencing. See attached photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/09/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel (x4)		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:	Anchored		
Corrective Action:		Date:	

Type: Emission Control Device	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:	Anchored. (ACCORDING TO COGCC MAPS, LOCATION IS IN FLOOD PLAINS)					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	100 BBLS	PBV FIBERGLASS		,	
Comment:	Anchored. (ACCORDING TO COGCC MAPS, LOCATION IS IN FLOOD PLAINS.)					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLS	FIBERGLASS AST		,	
Comment:	Anchored. (ACCORDING TO COGCC MAPS, LOCATION IS IN THE FLOOD PLAINS)					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	400 BBLs	STEEL AST		,
Comment:	Anchored (ACCORDING TO COGCC MAPS, LOCATION IS IN THE FLOOD PLAINS)				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 432869 Type: WELL API Number: 123-37329 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 432870 Type: WELL API Number: 123-37330 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; equipment disconnected. See attache photo.

Corrective Action:

Date:

Facility ID: 432872 Type: WELL API Number: 123-37331 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 432873 Type: WELL API Number: 123-37332 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 446738 Type: TANK API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday, September 9, 2019 at approximately 10:25, I, Inspector Brittani Santistevan, conducted an on-site inspection at ALM 33V-HZ SOUTH PAD (PDC Energy), at location #: 432871 in WELD COUNTY Colorado.</p> <p>While there, I observed a producing facility, and one TA wellhead.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. Unused/disconnected equipment inside ALM 33W-314 fencing. COMPLY WITH RULE 603.F. (Corrective Action Date: October 9, 2019) See attached photos #3,4 in individual wellhead photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	09/09/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402173294	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934581
679601524	Alm 33V-404	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934561
679601525	Alm 33V-234	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934562
679601526	Alm 33W-314	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934563
679601527	Alm 33W-404	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934564
679601528	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934565