

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2019

Submitted Date:

09/11/2019

Document Number:

679705397

**FIELD INSPECTION FORM**

Loc ID 315966 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 100 CHEVRON USA INC  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Sanford, Anita  |              | atlx@chevron.com           |         |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 231817      | WELL | PR     | 02/01/2019  | OW         | 103-09488 | F V LARSON "B" 27X | PR          |

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 9-10-2019 at approximately 18:00, inspector Rick Moran, conducted a routine inspection at Chevron well F.V. Larson B27X in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Trash. Photo 2. Complete by 10-11-2019.
- 2) Unused rods. Photo 3. Complete by 10-11-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705397.

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |     |       |  |
|--------------------|-----|-------|--|
| Comment:           | 911 | Date: |  |
| Corrective Action: |     |       |  |

**Good Housekeeping:**

|                    |                          |       |            |
|--------------------|--------------------------|-------|------------|
| Type               | UNUSED EQUIPMENT         |       |            |
| Comment:           | Unused rods on location. |       |            |
| Corrective Action: | Comply with Rule 603.f . | Date: | 10/11/2019 |
| Type               | TRASH                    |       |            |
| Comment:           | Unused wood on location. |       |            |
| Corrective Action: | Comply with Rule 603.f . | Date: | 10/11/2019 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                     |     |       | corrective date |
|--------------------------|-----|-------|-----------------|
| Type: Deadman # & Marked | # 4 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Submersible Pump   | # 1 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 231817 Type: WELL API Number: 103-09488 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on subpump.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            |                         |                       |               |                          |         |

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402173182    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934483">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934483</a> |
| 679705398    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934481">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934481</a> |