

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2019

Submitted Date:

09/11/2019

Document Number:

679705409**FIELD INSPECTION FORM**Loc ID 314439 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON USA INCCity: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Sanford, Anita  |              | atlx@chevron.com           |         |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 228724      | WELL | PR     | 10/01/2018  | OW         | 103-05697 | RIGBY 1       | PR          |

**General Comment:**[COGCC Inspection Report Summary.](#)[On 9-11-2019 at approximately 18:00, inspector Rick Moran, conducted a routine inspection at Chevron well Rigby 1 in Rio Blanco county.](#)[During this inspection the following compliance issues were observed:](#)[1\) Well head sign missing "911". Photo 2. Complete by 10-11-2019.](#)[A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.](#)[This is a summary of inspection report 679705409.](#)

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment: Missing "911" on well head sign.

Corrective Action: Install sign to comply with Rule 210.b. Date: 10/11/2019

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                          |     |       |  |                 |
|--------------------------|-----|-------|--|-----------------|
| <b>Equipment:</b>        |     |       |  | corrective date |
| Type: Submersible Pump   | # 1 |       |  |                 |
| Comment:                 |     |       |  |                 |
| Corrective Action:       |     | Date: |  |                 |
| Type: Deadman # & Marked | # 4 |       |  |                 |
| Comment:                 |     |       |  |                 |
| Corrective Action:       |     | Date: |  |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |                            |       |      |             |           |         |    |               |    |
|----------------------|----------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 228724                     | Type: | WELL | API Number: | 103-05697 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                            |       |      |             |           |         |    |               |    |
| Comment:             | Producing well on subpump. |       |      |             |           |         |    |               |    |
| Corrective Action:   |                            |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            |                         |                       |               |                          |         |

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402173831    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935058">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935058</a> |
| 679705410    | inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935054">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4935054</a> |