

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2019

Submitted Date:

09/10/2019

Document Number:

689703519

**FIELD INSPECTION FORM**

Loc ID 335839 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name      | Phone | Email                                 | Comment                   |
|-------------------|-------|---------------------------------------|---------------------------|
| Kellerby, Shaun   |       | shaun.kellerby@state.co.us            |                           |
| Pesicka, Conor    |       | conor.pesicka@state.co.us             |                           |
| , Caerus Piceance |       | COGCC.inspections@caerusoilandgas.com | Piceance inspections only |
| Murray, Richard   |       | g.richard.murray@state.co.us          |                           |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name              | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 272636      | WELL | PR     | 02/01/2011  | GW         | 045-10110 | N.PARACHUTE EF06D D19 595  | PR          |
| 272637      | WELL | PR     | 05/01/2019  | GW         | 045-10109 | N. PARACHUTE EF04D D19 595 | PR          |

**General Comment:**

COGCC Inspection Report Summary  
On Tuesday 09/10/2019 at approximately 1415 hrs, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC N. PARACHUTE EF04D D19 595 Location # 335839 in Garfield County, Colorado  
During this inspection the following possible compliance issues were observed:  
No emergency services number (911) and no nearest road on battery sign.  
Install sign to comply with Rule 210.b.  
C.A. Date 10/11/2019  
6 unused 2" risers at wells.  
Lock Out/Tag Out unused flowline risers within 24 hours of receipt of this report. Comply with Rule 603.f.  
C.A. Date 10/11/2019  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

| Location   |  |        |                  |
|--|--|--------|------------------|
| <b>Lease Road:</b>                                     |  |        |                  |
| Type   | Access   |        |                  |
| comment:   |  |        |                  |
| Corrective Action:                                     |  | Date:  |                  |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                  |
| <b>Signs/Marker:</b>                                   |  |        |                  |
| Type   | CONTAINERS   |        |                  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  | Date:  |                  |
| Type   | WELLHEAD   |        |                  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  | Date:  |                  |
| Type   | BATTERY  |        |                  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  | Date:  |                  |
| Emergency Contact Number:                              |  |        |                  |
| Comment:   | No emergency services number (911) and no nearest road on battery sign.                                    |        |                  |
| Corrective Action:                                     | Install sign to comply with Rule 210.b.  |        | Date: 10/11/2019 |
| <b>Good Housekeeping:</b>                              |  |        |                  |
| Type   | UNUSED EQUIPMENT   |        |                  |
| Comment:   | 6 unused 2" risers at wells.   |        |                  |
| Corrective Action:                                     | Lock Out/Tag Out unused flowline risers within 24 hours of receipt of this report. Comply with Rule 603.f. |        | Date: 10/11/2019 |
| Overall Good: <input type="checkbox"/>                 |  |        |                  |
| <b>Spills:</b>   |  |        |                  |
| Type   | Area   | Volume |                  |
| In Containment: No                                     |  |        |                  |
| Comment:   |  |        |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                  |
| <b>Equipment:</b>                                      |  |        |                  |
| Type:  | Plunger Lift   | # 2    | corrective date  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| <b>Venting:</b>  |  |        |                  |
| Yes/No   | NO   |        |                  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| <b>Flaring:</b>  |  |        |                  |

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 272636 Type: WELL API Number: 045-10110 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 272637 Type: WELL API Number: 045-10109 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs  | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|-------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction        | Pass            |                         |                       |  |                          |         |
| Gradient Terraces | Pass            |                         |                       |  |                          |         |
|                   |                 | Gravel                  | Pass                  |  |                          |         |
|                   |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |         |
| Berms             | Pass            |                         |                       |  |                          |         |
|                   |                 | Compaction              | Pass                  |  |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 402172990    | INSPECTION SUBMITTED           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934269">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934269</a> |
| 689703520    | Inspection 689703519 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934260">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4934260</a> |