

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Barb wire in disrepair		
Corrective Action:	Comply with Rule 604.c		Date: 10/03/2019
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumed to surface		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel appears to be shut off		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 239895 Type: WELL API Number: 123-07683 Status: PR Insp. Status: IO

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Report shows it as producing at the time of this inspection it appears to be inactive electric panel appears to be shut off.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 9/18/2019 at approximately 1200hrs. Inspector Robbie Revas, Conducted an on-site inspection at the Jack Berger A #3 KP Kauffman, at API #05-123-07683 in Weld County Colorado. While there, I observed a wellsite report show it as PR at the time of this inspection it appears to be inactive the electric panel appears to be shut off.</p> <p>During this inspection the following compliance issues were observed:</p> <p>Fencing: Barbwire fence around WH is in disrepair. Comply with Rule 604.c CA date 10/03/2019. See photo #3.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure that compliance issues are addressed to comply with COGCC Rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	09/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300209	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4941135