

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/18/2019

Submitted Date:

09/19/2019

Document Number:

687905506**FIELD INSPECTION FORM**
 Loc ID 326687 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Shorty, Priscilla		pshorty@hilcorp.com	
Roland, Kandis		kroland@hilcorp.com	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Ray, Mandi	505-324-5122	mray@hilcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262950	WELL	PR	01/03/2003	GW	067-08698	PENROSE 1R	PR

**General Comment:**
[Site inspection and equipment inventory with photos at the end of this report.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road access off county road.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact information posted on sign.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chain link fence around wellhead.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 4		
Comment:	1-3" flowline from wellhead to separator. 1-2" flowline from separator dump valve to offsite produced water gathering system. 1-3" flowline from separator to meter house. 1-4" flowline from separator to offsite dogleg.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Could only locate 2 deadman marked. Others appear to have been removed.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 262950	Type: WELL	API Number: 067-08698	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing.			
Corrective Action:				Date:

--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Gravel	Pass					
Ditches	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention for chemical injection tank.
Rip Rap	Pass					
Compaction	Pass	Gravel	Pass			

Comment: [Stormwater BMP's are maintained and appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905519	Overview photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4941915">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4941915</a>