

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2019

Submitted Date:

09/19/2019

Document Number:

699300214**FIELD INSPECTION FORM**

Loc ID 318318 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	All Inspections
Pesika, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241098	WELL	PR	12/01/2017	OW	123-08886	SHELDON R. SICKLER 4	IO

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Weeds growing along center of road		
Corrective Action	Comply with Rule 603.f	Date:	09/29/2019

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	WH sign is old, faded and has wrong operator name.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	10/19/2019

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds overgrown on location		
Corrective Action:	Comply with Rule 603.f	Date:	09/29/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electric panel, transformer, meter box Fabricated steel pipe		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Barb wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, transformers and meter box		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241098 Type: WELL API Number: 123-08886 Status: PR Insp. Status: IO**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well appears to be inactive electric panel appears to be shut off

Corrective Action: _____

Date: _____

COGCC Comments

Comment

COGCC Inspection Report Summary
 On Thursday 9/19/19 at approximately 0930 hrs. I, Inspector Robbie Revas,
 Conducted an on-site inspection at the Sheldon R. Sickler #4 KP Kauffman, at
 API #05-123-08886 in Weld County Colorado.
 While there, I observed a wellsite that appears to be inactive. The electric panel appears to
 be shut off.
 During this inspection the following possible compliance issues were observed:
 Sign issue: Current sign on location has the wrong operator information. Comply with Rule
 210.b CA date 10/19/2019 see photo #1
 Housekeeping: Weeds overgrown on access rd.
 and on location. Comply with rule 603.f CA date 9/29/2019 see all
 attached photos.
 Location is dry, weather is clear.
 A follow up on this site inspection needs to be conducted to ensure the
 Compliance issues have been corrected to comply with COGCC rules.
 Continuing education COGCC Inspection Report Summary.
 This is a summary of inspection report.

User

revasr

Date

09/19/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300215	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942264