

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2019

Submitted Date:

09/13/2019

Document Number:

699700003

**FIELD INSPECTION FORM**

Loc ID 334451 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Arauzo, Steven		steven.arauza@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	
Murray, Richard		g.richard.murray@state.co.us	

**General Comment:**

On September 4, 2019, COGCC Environmental Staff (John Heil and Steven Arauzo) conducted an environmental field inspection of LARAMIE ENERGY LLC (Laramie operator #10433) Laramie NVega 1D Location ID 334451 Spill ID 467076.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>					
Type	Area	Volume			
WELLHEAD					
Comment:	Active gas leak from a valve on the north side of Delta 27-321 (077-09334) wellhead. Operator was notified via cell phone on 9/4/2019.				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date:	09/14/2019

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: 10

Comment: COGCC staff observed a 45 feet by 45 feet by 3 feet deep excavation where the tank battery was located (northwest side of the pad, see photos). At time of inspection, Operator was on location delineating the spill with a PID while a mini excavator removed the impacted material. Operator indicated that the impacted material was being hauled off and that the stockpiled soil on location is clean and will be used backfilling the excavation. Operator discovered additional impacted soil around a flowline riser to the north of the tank battery. Operator shall comply with COAs on Doc# 402167798.

Corrective Action:  Date:

Reportable: YES GPS: Lat  Long

Proximity to Surface Water:  Depth to Ground Water:

**Water Well Complaint:**

DWR Receipt Num:  Owner Name:  GPS :  Lat  Long

**Field Parameters:**

Sample Location:  Comment:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402176223	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937113">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937113</a>
699700022	20190904 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937111">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937111</a>