

Anderson 17-1
API: 05-103-40003
Inspection: 679705525



Photo 1. Tank battery.



Anderson 17-1
API: 05-103-40003
Inspection: 679705525



40.14523, -108.97311, 5684.6ft, 118°
09/20/2019 04:39:57 PM

Photo 2. Pump jack.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Anderson 17-1
API: 05-103-40003
Inspection: 679705525



Photo 3. Stained soil at crude oil tank valve.



Photo 4. Stained soil at crude oil tank valve.

Anderson 17-1
API: 05-103-40003
Inspection: 679705525



Photo 5. Low spot in tank berm.



Photo 6. Stack by pump jack without bird screen.

Anderson 17-1
API: 05-103-40003
Inspection: 679705525



Photo 7. Uncapped flowlines.



Photo 8. Flowline filled with oil to top.

Anderson 17-1
API: 05-103-40003
Inspection: 679705525



Photo 9. Two split 10 foot long flowlines sections located 80 feet north of pump jack.



Photo 10. Rod & timbers.