

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/16/2019

Submitted Date:

09/16/2019

Document Number:

679705458

FIELD INSPECTION FORM

Loc ID 314851 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 200502
Name of Operator: 31 OPERATING
Address: 3021 RIDGE RD #156
City: ROCKWALL State: TX Zip: 75032

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------|
| Pesicka, Conor | 970-415-0789 | conor.pesicka@state.co.us | |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us | |
| Freeman, Kris | 254-727-0435 | kfreeman@31operating.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 229756 | WELL | PR | 02/19/1972 | GW | 103-07413 | GOVERNMENT 2-34 | PR |

General Comment:

[COGCC Inspection Report Summary.](#)

On 9-19-2019 at approximately 14:30, inspector Rick Moran, conducted a routine inspection at 31 Operating well Government 2-34 in Rio Blanco county.

During this inspection the following compliance issues were observed:

- 1) Stormwater sediment movement from location hillside flowing across location, and towards the White River. Photos 1, 2, 3, 4, 5, 6. Complete by 10-16-2019.
- 2) Battery sign is missing. Photo 7 & 8. Complete by 10-16-2019.
- 3) Container missing contents label. Photo 9. Complete by 10-16-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705458.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | CONTAINERS | | |
| Comment: | Missing contents label on container. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 10/16/2019 |

Emergency Contact Number:

Comment: Battery sign is missing. The side of the meter building does have the nearest public road.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 10/16/2019

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | | | corrective date |
|----------------------|---|-------|-----------------|
| Ancillary equipment | # 1 | | |
| Comment: | Container of unknown contents. | | |
| Corrective Action: | | Date: | |
| Horizontal Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Deadman # & Marked | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Gas Meter Run | # 1 | | |
| Comment: | Foundation of meter bulding is partially undercut by stormwater soil removal. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 229756 Type: WELL API Number: 103-07413 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Ditches | Fail | Culverts | Pass | Material Handling And Spill Prevention | Pass | |
| Sediment Traps | Fail | Other | Fail | | | |

Comment: [Stormwater sediment movement from the location hillside flowing across location, and towards the White River. The inspector followed the sediment trail from the location to the culvert going under Hwy 64. The White River is located ~100 yards from Hwy 64. One of the stormwater channels goes down the edge of the lease road.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 10/16/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402178685 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4938897 |
| 679705459 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4938892 |