

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2019

Submitted Date:

09/16/2019

Document Number:

699700004

**FIELD INSPECTION FORM**

Loc ID 322310 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS Professional
Fischer, Alex		alex.fischer@state.co.us	
Rollins, Blair		brollins@caerusoilandgas.com	
Arauza, Steven		steven.arauza@state.co.us	
, Caerus		COGCC.inspections@caerusoilandgas.com	All inspection
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210243	WELL	SI	08/10/2017	DSPW	045-05208	DIVIDE CREEK UNIT 12-WD	EI

**General Comment:**

On September 4, 2019, COGCC Environmental Staff (John Heil and Steven Arauza) conducted an environmental field inspection of CAERUS PICEANCE LLC (Caerus operator #10456) Divide Creek Unit Location ID 322310. Weather was sunny and temperatures about 70 degrees Fahrenheit.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Active drip coming from the 2000 BBL Produced Water AST loadout valve (See photos).  
Operator was contacted via cell phone on September 4, 2019.

Corrective Action:

Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,  
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.  
Properly treat or dispose of oily waste in accordance with 907.e.Date: 09/17/2019Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

LOCATION

Comment:

Location fencing in disrepair (See photos).

Corrective Action:

Repair fencing.

Date: 10/16/2019**Equipment:**

corrective date

Type: Flow Line

#

Comment:

Unmarked flowline located northeast of the wellhead (See photos).

Corrective Action:

Comply with Rule 603.f.

Date: 09/17/2019**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 210243 Type: WELL API Number: 045-05208 Status: SI Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402177570	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4938096">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4938096</a>
699700023	20190904 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4938093">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4938093</a>