

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08737
Date: 9-16-2019



Photo 1. View of the project area from the northeastern edge facing center.



Photo 2. View of the southern fill slope. Little desirable vegetation observed on the fill slope.



Photo 3. View of northern cut-slope from the northeastern edge facing westward. Little desirable vegetation observed here. Observable vegetation is largely comprised of Russian thistle (*Salsola tragus*). Slope appears to be recently seeded, although no mulch or erosion control practices observed.



Germination Transect
067-08737
9/16/2019

09.16.2019

Photo 4. View of the beginning of germination transect facing westward.



Photo 5. Birdseye view of typical seedling within germination quadrat. It is not apparent whether seedling is alive.



Photo 6 View from the end of germination transect facing eastward.



Photo 7. View of are in the southwestern well pad where cobble BMP is not sufficient and erosion continues. Surrounding soils are not stabilized.



Photo 8. View of reference area vegetation facing northward, east of well pad.