

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-06512
Date: 9-16-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the southern fill slope facing westward. Slope is not stabilized as weedy kochia is preventing desirable vegetation establishment and bare soils are eroding.



Photo 3. View of northern project area from the northeastern corner facing westward. Revegetation of perennial grasses such as smooth brome, is progressing within portions of the interim reclamation area; although dense kochia is threatening successful revegetation.



Photo 4. View of dense Canada and musk thistles within the southeastern project area.



Photo 5. View of reference area vegetation, east of the project area, facing northward.