

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2019

Submitted Date:

09/24/2019

Document Number:

699300243**FIELD INSPECTION FORM**

Loc ID 318436 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241290	WELL	SI	06/01/2019	OW	123-09078	MAHONEY 2	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	dead weeds all along acces road		
Corrective Action:	Comply with Rule 603.f	Date:	07/23/2019

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	WEEDS		
Comment:	Dead weeds completly covering electric panel		
Corrective Action:	Comply with Rule 603.f	Date:	07/23/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Does not appear to be plmbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		

Inspected FacilitiesFacility ID: 241290 Type: WELL API Number: 123-09078 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 9/24/19 at approximately 1230 hrs. I, Inspector Robbie Revas, Conducted an on-site Follow up inspection at the Mahoney #2 KP Kauffman, at API #05-123-09078 in Weld County Colorado.</p> <p>While there, I observed Wellsite.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>No current MIT submitted, Comply with Rule 326.b Produce well after performing successful mechanical integrity test per Rule 326.b or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. CA date 10/24/19</p> <p>Access road: Rule 603.f Weeds completely overgrown on access road has not been addressed and are now dead this Compliance issue is delinquent per Doc. #693500607 CA date 7/23/2019 See photo #3</p> <p>Weeds: Rule 603.f Weeds around electric panel have not been addressed and are now dead this Compliance issue is delinquent per Doc. #693500607 CA date 7/23/2019 See attached photo # 4.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	09/24/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300244	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946273