



Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Trash on and around PU		
Corrective Action:	Comply with Rule 603.f		Date: <u>10/01/2019</u>
Type	OTHER		
Comment:	Stained soil under PU gas engine		
Corrective Action:	Comply with Rule 603.f		Date: <u>10/09/2019</u>
Type	WEEDS		
Comment:	Dead weeds on location around flow lines		
Corrective Action:	Comply with Rule 603.f		Date: <u>10/01/2019</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	barbwire fence in disrepair		
Corrective Action:	Comply with Rule 604.c(2)M		Date: <u>10/09/2019</u>
<b>Equipment:</b>			
Type: Prime Mover	# 1		corrective date
Comment:	Gas engine		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Does not appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241340 Type: WELL API Number: 123-09129 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Tuesday 9/24/2019 at approximately 1430 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at Dechant-State #5 KP Kauffman, at API #05-123-09129 in Weld County Colorado.                      While there, I observed a Wellsite. Report shows it as SI Since 9/2018. During this inspection the following possible compliance issues were observed:                      No current MIT submitted, Comply with Rule 326.b Produce well after performing successful mechanical integrity test per Rule 326.b or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. CA date 10/24/19 Housekeeping: Dead weeds on/around PU and WH. Comply with Rule 603.f CA date 10/1/2019 See photos #3, 4 and 6. Housekeeping: Trash on and by PU, Comply with Rule 603.f CA date 10/1/2019 see photos #5 and 7 Fencing: Barbwire fence around WH and PU in disrepair, Comply with Rule 604.c(2)M CA date 10/9/2019 see photos #3 and 4. Location is dry, weather is clear.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	09/24/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300248	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946275">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946275</a>