

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2019

Submitted Date:

09/17/2019

Document Number:

694900416

FIELD INSPECTION FORM

Loc ID 335120 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

20 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, vanguard		sgghan@vnrenergy.com	SR. EH&S
, vanguard		scollett@vnrenergy.com	
, vanguard		aaxelson@vnrenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291271	WELL	PR	11/20/2007	GW	045-14322	GEISKE 43C-26-692	PR
291273	WELL	PR	11/21/2007	GW	045-14323	GEISKE 42A-26-692	PR
291308	WELL	PR	05/09/2013	GW	045-14330	GEISKE 32B-26-692	PR
291314	WELL	PR	11/24/2007	GW	045-14325	GEISKE 32D-26-692	PR
297963	WELL	PR	05/21/2009	GW	045-17004	GEISKE 41B-26-692	PR
297964	WELL	PR	05/21/2009	GW	045-17005	GEISKE 41A-26-692	PR
297965	WELL	PR	05/15/2009	GW	045-17006	GEISKE 42C-26-692	PR
297966	WELL	PR	05/15/2009	GW	045-17007	GEISKE 42D-26-692	PR
297967	WELL	PR	05/15/2009	GW	045-17008	GEISKE 43D-26-692	PR
297968	WELL	PR	05/18/2009	GW	045-17009	GEISKE 32C-26-692	PR
297969	WELL	PR	05/18/2009	GW	045-17010	GEISKE 42B-26-692	PR

General Comment:

[COGCC Inspection Report Summary](#)
On Tuesday 9/17/19 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Vanguard Geiski, at Location # 335120 in Garfield County, Colorado.
While there, I observed normal production operations.
During this inspection the following possible compliance issues were observed:
Staining in tank battery around load out bucket.
Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location			
Lease Road:			
Type	Main		
comment:			
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	staining in battery by load out bucket		
Corrective Action:	remove staining		Date: 10/17/2019
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:			Date:
Equipment:			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:			Date:

Type: Bird Protectors	# 14		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	chemical tanks		
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	2 tanks are in a seperate containment			
Corrective Action:				Date:

Venting:

Yes/No	YES	
Comment:	braden heads are open	
Corrective Action:		Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291271	Type:	WELL	API Number:	045-14322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	291273	Type:	WELL	API Number:	045-14323	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	291308	Type:	WELL	API Number:	045-14330	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	291314	Type:	WELL	API Number:	045-14325	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	297963	Type:	WELL	API Number:	045-17004	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	297964	Type:	WELL	API Number:	045-17005	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	297965	Type:	WELL	API Number:	045-17006	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				
Facility ID:	297966	Type:	WELL	API Number:	045-17007	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing				Date:				
Corrective Action:					Date:				

Facility ID: <u>297967</u>	Type: <u>WELL</u>	API Number: <u>045-17008</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>producing</u>			
Corrective Action:		Date:		
Facility ID: <u>297968</u>	Type: <u>WELL</u>	API Number: <u>045-17009</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>producing</u>			
Corrective Action:		Date:		
Facility ID: <u>297969</u>	Type: <u>WELL</u>	API Number: <u>045-17010</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>producing</u>			
Corrective Action:		Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				
		Waddles				
Ditches		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402181166	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4940938
694900426	694900416	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4940923