

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/18/2019

Submitted Date:

09/18/2019

Document Number:

699300202**FIELD INSPECTION FORM**
 Loc ID 318387 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241202	WELL	PR	11/03/1976	OW	123-08990	UPRR 42 PAN AM AF 2	PR

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Faded well name not legible		
Corrective Action:	Comply with Rule 210.e		Date: 10/18/2019
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Spoty stained soil around wH and under flowline		
Corrective Action:	Comply with Rule 907.e		Date: 10/18/2019
Type	OTHER		
Comment:	Mechanical issue PU appears to have a leaking gasket		
Corrective Action:	Comply with Rule 605.d		Date: 10/18/2019
Type	WEEDS		
Comment:	Weeds growing around Electric transformer.		
Corrective Action:	Comply with rule 603.f		Date: 09/28/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog fence		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric transformers, electric panel and meter box.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241202 Type: WELL API Number: 123-08990 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 9/18/2019 at approximately 1030hrs. Inspector Robbie Revas, Conducted an on-site inspection at the UPRR 42 Pan Am AF #2 KP Kauffman, at</p> <p>API #05-123-08990 in Weld County Colorado. While there, I observed a producing wellsite. During this inspection the following possible compliance issues were observed:</p> <p>Housekeeping: Weeds growing around electric transformers. Comply with rule 603.f 10 days for weeds. CA date 9/28/2019 see photo #3.</p> <p>Housekeeping: Spotty stained soil around WH and under flow line. Comply with Rule 907.e 30 days to remove stained soil. CA date 10/18/2019. See photos #4 and 5.</p> <p>Mechanical condition: PU appears to have a leaking gasket. Comply with Rule 605.d Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. CA date 10/18/2019 See photo # 6.</p> <p>Signs: WH sign is faded wellsite name is not legible. Comply with Rule 210.e Install/Replace sign. CA date 10/18/2019 See photo #1.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	09/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402180888	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4940691
699300203	Loction pics.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4940687