

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2019

Submitted Date:

09/16/2019

Document Number:

680305578

FIELD INSPECTION FORM

Loc ID 312242 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 55030

Name of Operator: MCCARTNEY ENGINEERING LLC

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
McCartney, Ron	(303) 830-7208	ron@mccartneyengineering.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219789	WELL	SI	08/01/2016	OW	075-07216	RICE 2	UN

General Comment:

Routine Site Inspection 2019

Note to Operator: Please read FIR completely and send Form 42 response when all CA's have been performed for follow-up reinspection.

Location				
Lease Road:				
Type	Access			
comment:	Lease road is heavily rutted, exhibiting erosion and lack of BMP's.			
Corrective Action	Repair and maintain lease roads per Rule 604 series.			Date: 10/14/2019
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Satisfactory			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Satisfactory			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:	Remove cement from previous work-over conversion to IJ, dated 04/16/2019.			
Corrective Action:	Remove surface debris/trash per Rule 604 series.			Date: 09/27/2019
Type	UNUSED EQUIPMENT			
Comment:	Well has been converted to IJ. Remove PJ from location.			
Corrective Action:	Remove unused equipment per Rule 603 series			Date: 12/16/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type				
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Other	# 0			corrective date
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 219789 Type: WELL API Number: 075-07216 Status: SI Insp. Status: UN**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: DSND

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 04/16/2019

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: Well has been converted to IJ. Update well file/well status/production reports.

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Idle WellPurpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Well has been converted to IJ since April 2019.
NOTE TO OPERATOR: Update/change well status on COGCC database.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	Fail			

Comment: [Use BMP's for erosion management.](#)

Corrective Action: [Lease road is exhibiting rutting from erosion. Repair \(fill ruts\) and grade, maintain lease road per Rule 1002 series.](#)

Date: 10/14/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402178820	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939055
680305578	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4945121
680305579	Wellhead - PJ (unused equipment)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946557
680305580	Debris	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946552
680395579	Wellhead - PJ (unused equipment)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946533