

Inspection Photos

API: 05-071-09838

Operator: ARP PRODUCTION COMPANY
WAPITI OPERATING LLC

Inspection Date: 9/23/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-09838 | Date: 9/23/2019

Inspection Photos



Photo 1. The culvert along the main road has partially filled in with sediment. It appears to have been cleaned out since the previous inspection but requires ongoing maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 9/23/2019

Inspection Photos



Photo 2. The culvert has been cleaned out from sediment buildup.
Lat/Long:37.02425,-104.82919



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 9/23/2019

Inspection Photos



Photo 3. There is List B noxious weeds growing at the location. (Musk thistle shown in photo). Corrective action was not completed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 9/23/2019

Inspection Photos



Photo 4. Noxious weeds have not been controlled at the location and have developed seed heads

Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 9/23/2019

Inspection Photos



Photo 5. Noxious weeds have not been controlled at the location and have developed seed heads which are dispersing seed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09838 | Date: 9/23/2019