

# Inspection Photos

API: 05-071-09061

Operator: ARP PRODUCTION COMPANY

WAPITI OPERATING LLC

Inspection Date: 9/23/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 9/23/2019

## Inspection Photos



**Photo 1.** Facing toward the location. Red arrow points to erosion issues that have not been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 9/23/2019

## Inspection Photos



**Photo 2.** Facing toward the location. Red arrow points to erosion issues that have not been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 9/23/2019

## Inspection Photos



**Photo 3.** There is List B noxious weeds growing along the cut slope. (Hounds tongue shown in photo)

Corrective action was not completed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 9/23/2019

## Inspection Photos



**Photo 4.** There is List B noxious weeds growing along the cut slope. (Musk thistle shown in photo)

Corrective action was not completed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-09061 | Date: 9/23/2019