

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2019

Submitted Date:

09/25/2019

Document Number:

696300626

FIELD INSPECTION FORM

Loc ID 318940 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 49407

Name of Operator: KUGLER* DEAN & JOE DBA D-J OIL COMPANY

Address: P O BOX 72

City: NEW RAYMER State: CO Zip: 80742

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

8 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Sutphin, Dirk		dirk.sutphin@state.co.us	
Kugler, Dean		dlkug@yahoo.com	
Kraich, Adam		adam.kraich@state.co.us	
,		dakugler@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242543	WELL	SI	12/01/2015	OW	123-10334	MYERS F-1	PA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds are actively growing on the entire location, see photos		
Corrective Action:	Comply with Rule 603.f .	Date:	10/04/2019
Type	TRASH		
Comment:	Trash on the Southeast side of pumping unit, see photo		
Corrective Action:	Comply with Rule 603.f .	Date:	10/04/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Well Bore is open to atmosphere, please install Nighthcap or Cut and Capped casing		
Corrective Action:	Comply with Rule 605.c.	Date:	10/04/2019
Type: Vertical Heater Treater	# 1		
Comment:	Unused Equipment		
Corrective Action:	Comply with Rule 603.f .	Date:	11/25/2019
Type: Deadman # & Marked	# 4		
Comment:	Unused Equipment		
Corrective Action:	Comply with Rule 603.f .	Date:	11/25/2019
Type: Pump Jack	# 1		
Comment:	Unused Equipment		
Corrective Action:	Comply with Rule 603.f .	Date:	11/25/2019

Type: Bradenhead	# 0	
Comment:	Does not appear to be plumbed to surface	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	Unused Equipment				
Corrective Action:	Comply with Rule 603.f .				Date: 11/25/2019

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.638020,-103.855310
Comment:	Unused Equipment				
Corrective Action:	Comply with Rule 603.f .				Date: 11/25/2019

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 242543 Type: WELL API Number: 123-10334 Status: SI Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 09/19/2019 at approximately 12:31, I, Inspector Erica Petrie, conducted a Field Inspection at Kugler* Dean and Joe DBD D-J Oil Company, Meyer F-1 at Location #318940 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>An open Well Bore, it appears that the Well has been recently Plugged and left with a well bore open to atmosphere. Well needs to have a Nightcap installed or cut and capped, see photo 5. Comply with Rule 605.c. Corrective Action Date 10/04/2019.</p> <p>Trash on the Southeast side of Pumping Unit, see photo 3. Comply with Rule 603.f. Corrective Action Date 10/25/2019.</p> <p>Weeds are actively growing on the entire location, see photos. Comply with Rule 603.f. Corrective Action Date 10/09/2019.</p> <p>Multiple Unused Equipment: Heater Treater, Pumping Unit, Horse's Head, Wellhead parts and fittings, Engine, Engine Shed, Crude Oil Tank, and Produced Water Tank. Comply with Rule 603.f. Corrective Action Date 11/25/2019.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Educational Inspections</p>	petrie	09/25/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300627	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946681