

Inspection Photos  
Location Name: IRELAND 14-32 TR  
API#: 05-071-09384  
INSP. #: 695101418



**PHOTO 1: WELLHEAD**

**PHOTO 2: WELL SIGN**

Inspection Photos  
Location Name: IRELAND 14-32 TR  
API#: 05-071-09384  
INSP. #: 695101418



**PHOTO 3: AREA OF STAINED SOIL APPEARS TO BE FROM HYDRAULIC HOSES OR DRIVEHEAD FITTING. "Properly treat or dispose of oily waste in accordance with 907.e." CA DATE 10-25-19**