

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

PHOTO 3: AREA OF STAINED SOIL APPEARS TO BE FROM HYDRAULIC HOSES OR DRIVEHEAD FITTING.

Corrective Action:

"Properly treat or dispose of oily waste in accordance with 907.e."

Date: 10/25/2019

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Compressor

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

TELEMETRY EQUIPMENT

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

PLUMBED TO SURFACE

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 292157 Type: WELL API Number: 071-09384 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101419	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4947441