

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/19/2019

Submitted Date:

09/19/2019

Document Number:

693200408**FIELD INSPECTION FORM**
 Loc ID 323864 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Caerus		COGCC.inspections@caerus oilandgas.com	<a href="#">All Piceance inspections</a>
Longworth, Mike		michael.longworth@state.co.u s	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

**General Comment:**
[Engineering Integrity Inspection performed on September 19, 2019. In response to FIU inspection 689703474](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<p>Corrective Actions noted in inspection 689703474 for</p> <p>"1" riser at separator, 3 open ended 1" risers at well, 3 open ended 1"risers in the weeds in north east corner of location between well and tank. Stained ground under open lines."</p> <p>1" Flowlines riser at wellhead have been marked, 3 flowlines on the noeth east coner have not been addressed</p> <p>See photo log</p>		
Corrective Action:	<p>24 hrs to lock out tag out. 30 days to remove riser.</p> <p>Provide annual pressure test results for 1" flowlines and location flowlines. Via FIR Resolution and email to Western Integrity inspector</p>	Date:	09/30/2019

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402182987	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942272">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942272</a>
693200409	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942259">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942259</a>