

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2019

Submitted Date:

09/19/2019

Document Number:

699300214**FIELD INSPECTION FORM**

Loc ID 318318 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241098	WELL	PR	12/01/2017	OW	123-08886	SHELDON R. SICKLER 4	IO

**General Comment:**

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Weeds growing along center of road		
Corrective Action	Comply with Rule 603.f	Date:	09/29/2019

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	WH sign is old, faded and has wrong operator name.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	10/19/2019

<b>Emergency Contact Number:</b>		
Comment:		
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds overgrown on location		
Corrective Action:	Comply with Rule 603.f	Date:	09/29/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Fabricated angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electric panel, transformer, meter box Fabricated steel pipe		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Barb wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, transformers and meter box		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 241098 Type: WELL API Number: 123-08886 Status: PR Insp. Status: IO**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well appears to be inactive electric panel appears to be shut off

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

## Comment

**COGCC Inspection Report Summary**

On Thursday 9/19/19 at approximately 0930 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Sheldon R. Sickler #4 KP Kauffman, at API #05-123-08886 in Weld County Colorado.

While there, I observed a wellsite that appears to be inactive. The electric panel appears to be shut off.

During this inspection the following possible compliance issues were observed:

Sign issue: Current sign on location has the wrong operator information. Comply with Rule 210.b CA date 10/19/2019 see photo #1

Housekeeping: Weeds overgrown on access rd.

and on location. Comply with rule 603.f

CA date 9/29/2019 see all

attached photos.

Location is dry, weather is clear.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

Continuing education COGCC Inspection Report Summary.

This is a summary of inspection report.

## User

## Date

revasr

09/19/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402182989	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942273">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942273</a>
699300215	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942264">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942264</a>