

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2019

Submitted Date:

09/19/2019

Document Number:

699300224

**FIELD INSPECTION FORM**

Loc ID 336205 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240431	WELL	PR	09/01/2017	OW	123-08219	VONASEK 3	SI
284846	WELL	SI	01/01/2018	GW	123-23884	DEBEQUE V 27-1	SI

**General Comment:**

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil under flow line valve		
Corrective Action:	Comply with Rule 907.e	Date:	10/19/2019
Type	UNUSED EQUIPMENT		
Comment:	PU removed from WH		
Corrective Action:	Comply with Rule 603.f	Date:	10/19/2019
Type	OTHER		
Comment:	Mechanical issue possible leaking flow line valve		
Corrective Action:	Comply with 605.d	Date:	10/19/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Kerr McGee WH has AG fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor Not connected		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Removed from WH sitting in side of location		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240431 Type: WELL API Number: 123-08219 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI PU removed from WH

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 284846 Type: WELL API Number: 123-23884 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

## Comment

COGCC Inspection Report Summary  
 On Thursday 9/19/19 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Vonasek #3 KP Kauffman, at API #05-123-08219 in Weld County Colorado.  
 While there, I observed SI Wellsite. The report show it to be producing, at the time of this inspection it appears to be SI as the PU has been removed and is sitting along the south side of location.  
 Shared location with Kerr McGee well.  
 During this inspection the following compliance issues were observed:  
 Housekeeping: unused equipment. Comply with rule 603.f, 30 days for unused equipment when machinery is not required to remove the equipment. 90 days for unused equipment when machinery is required to remove the equipment. CA date 12/19/2019 see photo #2  
 Mechanical issue: possible leaking valve. Comply with Rule 605.d, securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. CA date 10/19/2019 see photo #3  
 Housekeeping: Stained soil under flow line valve. Comply with Rule 907.e 30 days to remove stained soil. CA date 10/19/2019 see photo #3  
 Location is dry, weather is clear.  
 Continuing education COGCC Inspection Report Summary.  
 This is a summary of inspection report.

## User

revasr

## Date

09/19/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402182992	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942277">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942277</a>
699300225	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942269">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942269</a>