

**Inspection Photos**  
**Location Name: Champlin 117 AMOCO 1#2**  
**Location ID: 320151**



**Photo 1 WH**



**Photo 2 Unused equipment PU base and weeds on locatin**



**Inspection Photos**  
**Location Name: Champlin 117 AMOCO 1#2**  
**Location ID: 320151**



**Photo 3 Guy line anchor not properly marked and weeds on location**



**Photo 4 Weeds on entire location.**