

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2019

Submitted Date:

09/20/2019

Document Number:

688305774**FIELD INSPECTION FORM**

Loc ID 432850 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 19160Name of Operator: CONOCO PHILLIPS COMPANYAddress: 925 N ELDRIDGE PARKWAYCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email  | Comment                         |
|----------------|-------|--|---------------------------------|
| Smith, Larry   |       | <a href="mailto:larry.r.smith@conocophillips.com">larry.r.smith@conocophillips.com</a>   |                                 |
| ConocoPhillips |       | <a href="mailto:COPColoradoReg@conocophillips.com">COPColoradoReg@conocophillips.com</a> | <a href="#">All Inspections</a> |
| Burn, Diana    |       | <a href="mailto:diana.burn@state.co.us">diana.burn@state.co.us</a>                       |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 432851      | WELL | PR     | 09/29/2013  | OW         | 005-07208 | Zukowski 17 1H | PR          |

**General Comment:**[Annual Bradenhead Test Inspection/Routine Inspection](#)

**Location**Overall Good: ☒

|                      |         |       |  |
|----------------------|---------|-------|--|
| <b>Signs/Marker:</b> |         |       |  |
| Type                 | BATTERY |       |  |
| Comment:             |         |       |  |
| Corrective Action:   |         | Date: |  |

Emergency Contact Number:

Comment: 855-595-8258

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Fencing/:</b>   |             |       |  |
| Type               | PUMP JACK   |       |  |
| Comment:           |             |       |  |
| Corrective Action: |             | Date: |  |
| Type               | LOCATION    |       |  |
| Comment:           | barbed wire |       |  |
| Corrective Action: |             | Date: |  |

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| <b>Equipment:</b>  |     |       | corrective date |
| Type: Flow Line    | # 1 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |
| Type: Bradenhead   | # 1 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

### Location Construction

Location ID: 432851 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

**Comment:** Form: (04) 400539331 01/26/2014 1) The flaring of natural gas shall be allowed in accordance with COGCC Rule 912 for the initial production test period. 2) Notify the local emergency dispatch or the local governmental designee of any natural gas flaring. 3) Submit updated requests to flare to COGCC on Form 4 (Sundry Notice), which discuss whether or not any new gathering systems or increased development of the field have changed pipeline economics such that installation of a new pipeline would be an economically viable option in lieu of continued flaring. 4) The operator is required to obtain and maintain any required air permits from CDPHE. 5) The flare volumes shall be reported by Form 7, Operator's Monthly Report of Operations.

Corrective Action: Contact COGCC Engineer on Form 4 VENT\_FLARE updates.

Date: 10/04/2019

#### Wildlife BMPs:

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**Facility ID: 432851 Type: WELL API Number: 005-07208 Status: PR Insp. Status: PR**Producing Well**Comment: PR. Jul 2019 production last reported to COGCC database.

Corrective Action:

Date:

**BradenHead**Comment: Annual Bradenhead head test completed with inspector. Form 17 is attached. Initial Bradenhead pressure was -1.6 psi on automatic gauge and took 1 min on a vacuum to die thru a needle nose valve when opened. ISIP was 0 psi.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402184091    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4943013">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4943013</a> |
| 688305800    | COP Zukowski 17 1H   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942994">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4942994</a> |