

Inspection Photos

09/27/2019

Operator: OILFIELD SALVAGE & SERVICE CO -
65550

Location ID: 311709
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550
Location ID: 311709



Photo 1: Photo taken from the north end of the location, facing south. Photo shows additional reclamation appears to have been conducted, however, operator has seeded up the slope rather than along the contour. Seeding actives have not been conducted in accordance with good engineering practices and will likely facilitate erosion degradation.



Photo 2: Photo shows wattles on location have not been properly staked/trenched/backfilled in accordance with good engineering practices. BMP is not in proper functioning condition.

Inspection Photos

Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550

Location ID: 311709



Photo 3: See comments under photo 2.



Photo 4: Photo taken from the south end of the location. Photo shows operator has installed a berm. Berm remains loose and unconsolidated material. BMP has not been installed in accordance with good engineering practices.

Inspection Photos
Operator Name: OILFIELD SALVAGE & SERVICE CO - 65550
Location ID: 311709



Photo 5: Contined from photo 4. Photo shows area of the berm that has been “blown-out”. BMP is not in proper functioning condition.



Photo 6: Photo taken from the south end of the location, facing west. Photo shows areas to the west of the location where stormwater runoff from location deposited sediment. It does not appear as though these areas have had additional reclamation activities conducted, or BMPs installed.