

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/23/2019

Submitted Date:

09/24/2019

Document Number:

679705529**FIELD INSPECTION FORM**
 Loc ID 335694 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 110 W 7TH STREETCity: FORTH WORTH State: TX Zip: 76102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Reid, Van		van_reid@xtoenergy.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281423	WELL	PR	07/08/2010	GW	103-10646	PICEANCE CREEK UNIT T35X-2G9	PR
281424	WELL	PR	08/25/2009	GW	103-10647	PICEANCE CREEK UNIT T35X-2G8	PR
281427	WELL	PR	07/08/2010	GW	103-10648	PICEANCE CREEK UNIT T35X-2G7	PR
281428	WELL	PR	12/14/2018	OG	103-10649	PICEANCE CREEK UNIT T35X-2G6	PR
281429	WELL	PR	06/22/2008	GW	103-10650	PICEANCE CREEK UNIT T35X-2G5	PR
281430	WELL	PR	06/08/2012	GW	103-10651	PICEANCE CREEK UNIT T35X-2G4	PR
281431	WELL	PR	05/01/2019	GW	103-10652	PICEANCE CREEK UNIT T35X-2G3	PR
281432	WELL	PR	06/22/2008	GW	103-10653	PICEANCE CREEK UNIT T35X-2G2	PR
281433	WELL	PR	06/22/2008	GW	103-10654	PICEANCE CREEK UNIT T35X-2G1	PR

General Comment:

COGCC Inspection Report Summary.

On 9-23-2019 at approximately 11:45, inspector Rick Moran, conducted a routine inspection at XTO Energy wells Piceance Creek Unit T35X-2G in Rio Blanco county.

The following compliance issues were observed:

- 1) Tash of tubing & wood spool. Photo 3 & 4. Complete by 10-23-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705529.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash of chemical tubing & wood spool near separator.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/23/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 2		
Comment:	Two containers of MC MX 6-2719 with secondary containment.		
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Separator	# 1	
Comment:	In building.	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Well headers.	
Corrective Action:		Date:
Type: Deadman # & Marked	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		39.906280,-108.250180
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	281423	Type:	WELL	API Number: 103-10646 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	281424	Type:	WELL	API Number: 103-10647 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	281427	Type:	WELL	API Number: 103-10648 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	281428	Type:	WELL	API Number: 103-10649 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	281429	Type:	WELL	API Number: 103-10650 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	281430	Type:	WELL	API Number: 103-10651 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	281431	Type:	WELL	API Number: 103-10652 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		
Facility ID:	281432	Type:	WELL	API Number: 103-10653 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well on plunger lift.			
Corrective Action:		Date:		

Facility ID:	281433	Type:	WELL	API Number:	103-10654	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing well on plunger lift.

Corrective Action:		Date:	
--------------------	--	-------	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402186942	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4945581
679705542	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4945555