

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2019

Submitted Date:

09/24/2019

Document Number:

679705559

FIELD INSPECTION FORM

Loc ID 316373 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORTH WORTH State: TX Zip: 76102

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Arauzo, Steven		steven.arauza@state.co.us	
Heil, John		john.heil@state.co.us	
Reid, Van		van_reid@xtoenergy.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Dooling, Jessica	970-769-6048	Jessica_Dooling@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270456	WELL	PR	07/01/2019	GW	103-10401	YELLOW CREEK FEDERAL 3-45-1	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 9-24-2019 at approximately 15:45, inspector Rick Moran, conducted a routine inspection at Yellow Creek Federal 3-45-1 in Rio Blanco county.

The following compliance issues were observed:

- 1) Well head sign missing "911". Photo 5. Complete by 10-24-2019.
- 2) Contact COGCC EPS in reference to the line leak. Photo 4, 6, 7, 8, Complete by 9-26-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705559.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	"911" missing on well head sign.		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: <u>10/24/2019</u>

Overall Good:

Spills:			
Type	Area	Volume	
Produced Water			
Comment:	<p>On approaching the location the inspector observed water flowing down the lease road. On arrival at the location water was observed bubbling up from the ground near the pig station. The inspector estimated it was flowing out at 1 bbl every 3 to 5 minutes. XTO Energy was called in reference to the leak on their emergency number at 970-675-4117 @ 15:36. At 15:46 two XTO representatives arrived at the location and immediately accessed the situation and started procedures to stop the leak. The leak appeared to fully stop at 16:06. The water flowed approximately 200 feet down hill from the source.</p>		
Corrective Action:	Contact COGCC EPS staff regarding Rule 906.c.		Date: <u>09/26/2019</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment: Container of methanol with secondary containment.		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment: Equipment building.		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		39.991250,-108.371520
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	5	400 BBLs	STEEL AST		39.991250,-108.371520
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 270456 Type: WELL API Number: 103-10401 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well on plunger lift.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402187848	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946281
679705560	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946270