

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2019

Submitted Date:

09/24/2019

Document Number:

695101400**FIELD INSPECTION FORM**

Loc ID 308531 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273504	WELL	PR	07/12/2007	GW	071-08177	BEARLY 24-29	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
Produced Water	WELLHEAD	>= 5 bbls		
Comment:	PHOTO 3: APPEARS THAT PACKING WAS LEAKING ON WELLHEAD (NOT THERE IS NO LEAK AT TIME OF INSPECTION). IMPACTED AREA EXTENDS FROM WELLHEAD TO SOUTHWEST APP. 123'. PHOTO 4: ANOTHER PATH EXTENDING FROM WELLHEAD WEST AND THEN SOUTH FOR APP.93'. PHOTO 5: PHOTO SHOWING THAT THERE HAS BEEN OTHER EVENTS AS YOU CAN SEE THE WHITE CHALKY STAINING BEYOND THE CURRENT WET SOIL. WHITE CHALKY STAINING EXTENDS PAST CURRENT WET SOIL APP. 18'.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. CA DATE 9-25-19.			Date: 09/25/2019

In Containment: No

Comment:

☒ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 273504 Type: WELL API Number: 071-08177 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Complaint**

Comment:

THIS INSPECTION IS IN RESPONSE TO A COMPLAINT. DOC# . ON THE FIRST INVESTIGATION I FOUND THAT THE OPERATOR HAD A TEST COMPRESSOR AT THE START OF THE ROW TO THIS LOCATION. AT TIME OF INITIAL INVESTIGATION THE OPERATOR WAS IN THE PROCESS OF SHUTTING DOWN THE COMPRESSOR. THEY SAID TEST WAS NOT GOOD THEY WERE REMOVING THE COMPRESSOR. THAT COMPRESSOR WAS NOT ASSOCIATED WITH THIS WELL, IT WAS CONNECTED TO A GATHERING LINE NOT ASSOCIATED WITH THIS LOCATION. I SPOKE WITH COMPLAINTANT AND HE STATED THAT THE NOISE HAS BEEN REDUCED SINCE HIS COMPLAINT WAS FILED.

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402187625	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946103">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946103</a>
695101401	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946093">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946093</a>