

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e		Date: <u>06/02/2019</u>
Type	DEBRIS		
Comment:	Debris weeds: dead weeds around location		
Corrective Action:	Comply with Rule 603.f		Date: <u>05/16/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	does not appear to be plumbed to surface		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241700 Type: WELL API Number: 123-09489 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 9/24/19 at approximately 1130 hrs. I, Inspector Robbie Revas, Conducted an on-site Follow up inspection at the Elkhorn Company B #7 KP Kauffman, at API #05-123-09489 in Weld County Colorado. While there, I observed Wellsite. During this inspection the following possible compliance issues were observed: Stained soil: Rule 907.e this Compliance issue is delinquent per Doc. # 688402086 CA date 6/2/2019 See photo #3 Debris/weeds: Rule 603.f Has been partially addressed (dead weeds removed from PU and around Electric panel) it appears that the dead weeds around location have not been addressed creating compliance issue to be delinquent CA date 5/16/2019 See attached photos #2, 4, 5 and 6. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	09/24/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402187849	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946282
699300242	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946272