

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-08295
Date: 9-24-2019



Photo 1. View of repaired ditch and berm along the access road entrance.



Photo 2. View of cobble in ditch along access road. Cobble placed in this manner is not a BMP installed in accordance with good engineering practices. See CDOT erosion control and stormwater quality field guide for examples. This will need to be carefully monitored and if erosion continues here additional BMPs will need to be installed using good engineering practices.