

Inspection Photos
Operator: BP America
Location/API #: 067-07161
Date: 9-24-2019



Photo 1. View of western fill slope from the southwestern edge facing northward. Revegetation is largely comprised of smooth brome and ponderosa pine trees.



Photo 2. View of sediment catchment within the eastern project area needing maintenance. Additional BMPs to prevent sediment run-on are recommended.



Photo 3. View of reference area vegetation, comprised of mixed ponderosa pine and gambel oak woodland with grass field.