



Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		Date: _____
Corrective Action:	<input style="width: 100%;" type="text"/>		
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Trash on the Southeast side of pumping unit, see photo		
Corrective Action:	Comply with Rule 603.f .	Date:	10/04/2019
Type	WEEDS		
Comment:	Weeds are actively growing on the entire location, see photos		
Corrective Action:	Comply with Rule 603.f .	Date:	10/04/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Other	# 1		corrective date
Comment:	Well Bore is open to atmosphere, please install Nighthcap or Cut and Capped casing		
Corrective Action:	Comply with Rule 605.c.	Date:	10/04/2019
Type: Deadman # & Marked	# 4		
Comment:	Unused Equipment		
Corrective Action:	Comply with Rule 603.f .	Date:	11/25/2019
Type: Bradenhead	# 0		
Comment:	Does not appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Unused Equipment		
Corrective Action:	Comply with Rule 603.f .	Date:	11/25/2019

Type: Vertical Heater Treater	# 1	
Comment:	Unused Equipment	
Corrective Action:	Comply with Rule 603.f .	Date: 11/25/2019

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:	Unused Equipment				
Corrective Action:	Comply with Rule 603.f .				Date: 11/25/2019

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.638020,-103.855310
Comment:	Unused Equipment				
Corrective Action:	Comply with Rule 603.f .				Date: 11/25/2019

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 242543 Type: WELL API Number: 123-10334 Status: SI Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Thursday 09/19/2019 at approximately 12:31, I, Inspector Erica Petrie, conducted a Field Inspection at Kugler* Dean and Joe DBD D-J Oil Company, Meyer F-1 at Location #318940 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      An open Well Bore, it appears that the Well has been recently Plugged and left with a well bore open to atmosphere. Well needs to have a Nightcap installed or cut and capped, see photo 5. Comply with Rule 605.c. Corrective Action Date 10/04/2019.                      Trash on the Southeast side of Pumping Unit, see photo 3. Comply with Rule 603.f. Corrective Action Date 10/25/2019.                      Weeds are actively growing on the entire location, see photos. Comply with Rule 603.f. Corrective Action Date 10/09/2019.                      Multiple Unused Equipment: Heater Treater, Pumping Unit, Horse's Head, Wellhead parts and fittings, Engine, Engine Shed, Crude Oil Tank, and Produced Water Tank. Comply with Rule 603.f. Corrective Action Date 11/25/2019.                      A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.                      Continuing Educational Inspections</p>	petrie	09/25/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402188448	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946715">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946715</a>
696300627	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946681">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946681</a>