

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adquate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:	Trash on the Northeast side of pumping unit. See photo		
Corrective Action:	Comply with Rule 603.f .		Date: <u>11/01/2019</u>
Type	OTHER		
Comment:	Stained soil at wellhead, see photos		
Corrective Action:	Comply with Rule 907.e		Date: <u>11/01/2019</u>
Type	UNUSED EQUIPMENT		
Comment:	Unsed Pumping Unit and engine, engine housing, 4 deadman anchors, multiple chemical tanks, propane tank (500 gallons) See photos		
Corrective Action:	Comply with Rule 603.f.		Date: <u>12/02/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:			Date:
Type: Other	# 1		corrective date
Comment:	Open Wellbore, see photo 1. Please install Nightcap or Cut and Cap open wellbore		
Corrective Action:	Comply with Rule 605.c.		Date: <u>10/09/2019</u>
Venting:			
Yes/No			

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 246165 Type: WELL API Number: 123-13962 Status: SI Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 09/24/2019 at approximately 11:06, I, Inspector Erica Petrie, conducted a Field Inspection at Tindall Operating Company, Nickerson #4 at Location #326976 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: An open Well Bore, it appears that the Well has been recently Plugged and left with a well bore open to atmosphere. Well needs to have a Nightcap installed or cut and capped, see photo 1. Comply with Rule 605.c. Corrective Action Date 10/09/2019. Trash on the Northeast side of Pumping Unit, see photo 6. Comply with Rule 603.f. Corrective Action Date 11/01/2019. Stained Soil at Wellhead, see photos 1 and 5. Comply with Rule 603.f. Corrective Action Date 11/01/2019. Multiple Unused Equipment: Pumping Unit, Horse's Head, Wellhead parts and fittings, Engine, Engine Shed, Chemical Tanks/Pumps, and Propane Tank. See photos 2 & 3. Comply with Rule 603.f. Corrective Action Date 12/02/2019. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Educational Inspections</p>	petrie	09/25/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300629	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4952990