

Inspection Photos
Operator: BP America
Location/API #: 067-09080
Date: 9-30-2019



Photo 1. View of the project area from the northeastern corner facing center. Revegetation is largely comprised of a mixture of grasses such as intermediate wheatgrass, crested wheatgrass, and smooth brome.



Photo 2. View of sediment accumulation within cobble lined silt trap, needing maintenance.



Photo 3. View of erosion occurring around rock BMP within the western project area.



Photo 4. View of the western fill slope from the southwestern edge facing northward.



Photo 5. View of reference area vegetation, comprised of open ponderosa pine woodland and dense shrub understory dominated by gambel oak.