

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2019

Submitted Date:

09/26/2019

Document Number:

689500994

FIELD INSPECTION FORM

Loc ID 320208 Inspector Name: Oakman, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------|---------------------------------|
| , KPK | | cogcc@kpk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 119210 | PIT | | | | - | REUBEL 1-1 | EI |
| 203043 | WELL | SI | 06/01/2019 | GW | 001-08449 | RUEBEL ET AL 1-1 | EI |

General Comment:

COGCC Environmental Inspection to determine the status of pit facility ID 119210. Any corrective actions from previous inspections that have not been addressed are still applicable.

COGCC personnel found no surface indication of a pit present in the location. Records review and aerial photos found no evidence that there was a produced water pit on location; historic inspection reports document a concrete water vault on location. The pit status has been changed to closed, however, no associated remediation or site investigation has been conducted. Should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required.

Photos attached to document site condition at the time of inspection.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: [Stained soil at separator \(see photo 5\)](#)

Corrective Action: [Properly treat or dispose of oily waste in accordance with 907.e.](#)

Date: 10/19/2019

Overall Good:

Spills:

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Flow Line

#

corrective date

Comment: [Unused flowline risers observed between tanks and separator \(see photo 6\); Unmarked and inactive flowline risers are considered unused equipment.](#)

Corrective Action: [Comply with COGCC rule 603.f; 24 hours to lock out/ tag out unused flowline risers; all unused/ inactive flowline risers shall be removed by operator in 30 days.](#)

Date: 10/19/2019

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 119210 Type: PIT API Number: - Status: Insp. Status: EI

Facility ID: 203043 Type: WELL API Number: 001-08449 Status: SI Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402190059 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4947937 |
| 689500995 | Photo Log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4947926 |