

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/07/2019

Submitted Date:

10/08/2019

Document Number:

696101376**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 310743      Evins, Bret      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER      State: CO      Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296788	WELL	SI	05/01/2019	OW	123-26908	NORTH PLATTE 43-13	SI

**General Comment:**

This is a WELL inspection.  
 Well(s): 1; Shut-In | SI.  
 Battery: Active.

Centralized Battery serves 2 Location IDs (310744, 310743).  
 (Well(s): 2; Producing | PR) ; Well(s): 1; Shut-In | SI).

Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. See photo #1.			
Corrective Action:	Remove, manage, & control weeds around wellsite. Comply with Rule 603.f.			Date: 10/15/2019
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Bradenhead	# 1			corrective date
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type:	#			

Comment:	Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.				
Corrective Action:				Date:	
Type: Plunger Lift		# 1			
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.393270,-104.377729	
Comment:	Centralized Battery serves 2 Location IDs (310744, 310743). Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.					
Corrective Action:					Date:	

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	296788	Type:	WELL	API Number:	123-26908	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: PRODUCTION RECORDS									
<u>Comment:</u> Shut-In. Observed production valves shut. Last production: 04/2019.									
Corrective Action:									
Date:									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 10/07/2019 at approximately 14:08 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: North Platte /43-13 Pad  Location ID: 310743  Location County: Weld County, Colorado  Weather: Dry</p> <p>While there, I observed:  Well(s): 1; Shut-In   SI.  Battery: Active.</p> <p>Centralized Battery serves 2 Location IDs (310744, 310743).  (Well(s): 2; Producing   PR) ; Well(s): 1; Shut-In   SI).</p> <p>Refer to Field Inspection Doc. #696101374 and/or Location ID #310744 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issues were observed:  1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance.  Remove, manage, &amp; control weeds around wellsite.  Comply with Rule 603.f.  Corrective Action date: 10/15/2019.  See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/08/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101377	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957476">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957476</a>