

Inspection Photos

Operator: Kinder Morgan
Location/API #: 083-06715
Date: 10-3-2019



Photo 1. View of the project area from the southeastern edge facing center.



Photo 2. View of the southern portion of the interim reclamation area, returned to cultivation.



Photo 3. View of erosional channeling (approx. 2 feet wide and 4 inches deep) in eastern and southeastern interim reclamation area, from concentrated stormwater flows exiting the eastern edge of the well pad.



Photo 4. View of reference area comprised of dryland wheat cropfield, in mowed condition at this time.