

Inspection Photos

10/09/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC # 10112

Location ID: 303599
Yuma County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator Name: FOUNDATION ENERGY
MANAGEMENT LLC # 10112
Location ID: 303599



Photo 1: Photo taken from the north end of the location, facing southeast. Photos 1-3 provide an overview of the location from southeast, south to southwest. Photo shows erosion on the pad has been repaired. However, site remains unstabilized and soils loose; location remains at risk to erosion degradation. Photos also show no erosion control BMPs have been installed per CAS

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: FOUNDATION ENERGY
MANAGEMENT LLC # 10112
Location ID: 303599



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the location, facing west. See comments under photo 1.

Inspection Photos
Operator Name: FOUNDATION ENERGY
MANAGEMENT LLC # 10112
Location ID: 303599



Photo 5: Photo taken from the location, facing north. See comments under photo 1.



Photo 6: Photo from the south end of the location, facing south. Photo shows Operator has failed to repair/reclaim adjacent lands degraded due to stormwater runoff from the location. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: FOUNDATION ENERGY
MANAGEMENT LLC # 10112
Location ID: 303599



Photo 7: See comments under photo 6.



Photo 8: See comments under photo 6. Photo also shows sediment deposition into and intermittent stream.

Inspection Photos
Operator Name: FOUNDATION ENERGY
MANAGEMENT LLC # 10112
Location ID: 303599



Photo 9: See comments under photo 8.



Photo 10: See comments under photo 8.

Inspection Photos
Operator Name: FOUNDATION ENERGY
MANAGEMENT LLC # 10112
Location ID: 303599



Photo 11: Photo taken from an intermittent drainage south of the location, facing north. Photo shows stormwater runoff from the location has caused degradation to the adjacent lands, as well as sediment deposition in an intermittent drainage/stream. Photo also shows that operator has not conducted reclamation activities to repair the degradation, or installed stormwater and erosion control BMPs.