

# Inspection Photos

API: 05-061-06076

Operator: CHEMCO INC

Inspection Date: 10/7/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

## Inspection Photos



**Photo 1.** Facing southwest along the access road which has not been reclaimed. The crop has not re-established and there are undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

## Inspection Photos



**Photo 2.** Facing west toward the location. There is equipment that still remains at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

## Inspection Photos



**Photo 3.** There is a cement pad, shed, and pipe risers that remain.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

## Inspection Photos



**Photo 4.** The shed Has location name Wear #1, and the Operator name CHEMCO.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

## Inspection Photos



**Photo 5.** Facing east at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

## Inspection Photos



**Photo 6.** Facing toward the south side of the location. This area is bare of vegetation with no crop growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019

## Inspection Photos



**Photo 7.** Facing southeast toward the surrounding undisturbed crop field. Wheat stubble is shown to be uniformly established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06076 | Date: 10/7/2019