

Inspection Photos

API: 05-017-07453

Operator: RESOURCE DEVELOPMENT

Inspection Date: 10/7/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 1. Facing west at the beginning of the reclaimed access road. There are two wood posts that remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 2. Facing west along the former access road. There are areas along the road where vegetation is not established and soils appear to be compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 3. Facing west further along the access road. There is weedy vegetation along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 4. View of vegetation along the road is comprised mostly with *Medicago* sp. and Field bindweed which is a List C noxious weed. These species were not observed in the undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 5. Facing west toward the location. Vegetation has not adequately established and bare areas have compacted soils. It appears the soils were not cross ripped as required.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 6. Facing southeast. There are rows of compacted soil where vegetation is not growing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 7. West side of the location facing east. There are rows of compacted soil where vegetation is not growing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 8. West side of the location facing south. Vegetation has not adequately established in this area. Possible soil compaction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 9. There is an area of subsidence at the west side of the location which is approximately 80 ft. long x 10 ft. wide x 2ft. deep.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 10. There is another area of subsidence at the north side of the location which is approximately 3-4ft. deep. Red arrow points to 5 ft. shovel placed in the area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 11. Facing south at the north side of the location where subsidence occurred. Deep hole is a safety concern.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019

Inspection Photos



Photo 12. Facing north toward the undisturbed reference area which is mostly composed of Sideoats grama, Blue grama, and Sand dropseed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07453 | Date: 10/7/2019