

# Inspection Photos

API: 05-009-05182

Operator: TROJAN OIL & GAS COMPANY

Inspection Date: 10/8/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-009-05182 | Date: 10/8/2019

## Inspection Photos



**Photo 1.** Facing west toward the location. The area which does not have crop growth was stepped out to be approximately 130' x 60'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 10/8/2019



## Inspection Photos



**Photo 2.** Facing north toward the location. The area which does not have crop growth was stepped out to be approximately 130' x 60'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 10/8/2019

## Inspection Photos



**Photo 3.** Facing east toward the location. The area which does not have crop growth was stepped out to be approximately 130' x 60'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 10/8/2019



## Inspection Photos



**Photo 4.** Facing southeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 10/8/2019



## Inspection Photos



**Photo 5.** Plastic pipe remains at center of the location. Dug around the pipe but it is buried deep into the ground. Will need to be cut and capped 3 ft. below grade.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 10/8/2019



## Inspection Photos



**Photo 6.** The top six inches did not seem to be compacted but it was much more compacted past 6 inch depth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-009-05182 | Date: 10/8/2019